



LENCST | Conveyor heavy duty kit



Point 2: Multiplication of plates



PRESENTATION

The Conveyor heavy duty Kit prevents premature wear of the skid plate due to the fall of heavy objects or objects at high drop height.

- 2 reinforcement points:
- 1. Addition of PE skids under the skid plate.
- 2. Multiplication of the number of plates positioned (width divided by 2) in front of the glide floor with a ply joint for better rigidity.



Benefits

Maintains the service life of the skid plate for specific flows of heavy products, or in case of unsuitable object drop heights.



Prerequisite

- Spare conveyor belt or equipment required to lift the belt during the modification operation to avoid cutting it.
- · Study required for site installation.



Installation time on site

1 day of intervention minimum depending on the site configuration.





